02910.000080 PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Application of:)	Examiner: Evan T. Pert
SEIJI MISHIMA		;	Group Art Unit: 2826
Application No.: 10/665,425		:)	U.S. Patent No.: 7,037,158 B2
Filed: September 22, 2003		:	Issued: May 2, 2006
For:	METHOD FOR MANUFACTURING AN ELECTRON SOURCE SUBSTRATE	:) :	December 12, 2006

Commissioner for Patents P.O. Box 1450 Alexandria, Virginia 22313-1450

ATTENTION: CERTIFICATES OF CORRECTION BRANCH

CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

Patentee's undersigned attorney may be reached in our Washington, D.C.

office by telephone at (202) 530-1010. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Jack S. Cubert

Attorney for Patentee Registration No. 24,245

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800

Facsimile: (212) 218-2200

DC_MAIN 260031v1

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

7.037.158 B2

DATED

May 2, 2006

INVENTOR(S): SEIJI MISHIMA ET AL.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON THE COVER PAGE

:

(Item 56), U.S. Patent Documents, "6,836,304 B1" should read --6,836,304 B2--.

(Item 57), Abstract, "spacer" should read --spacer, --.

COLUMN 1

Line 15, "kinds" should read --kinds:--.

COLUMN 2

Line 8, "spacers" should read -- spacer -- .

COLUMN 3

Line 50, "n ink" should read -- an ink --. Line 54, "cations" should read --cations --.

COLUMN 5

Line 18, "tens" should read --tens of--.

COLUMN 8

Line 3, "next" should be deleted.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza

New York, New York 10112-3800 (212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30) DWP/klm DC MAIN 260031v1 PATENT NO. 7,037,158 B2

No. of add'l. copies @ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 7,037,158 B2

DATED : May 2, 2006

INVENTOR(S) : SEIJI MISHIMA ET AL.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 9

Line 33, "10" should read --110--.

Line 38, "in the" should be deleted.

Line 43, "10," should read --110,--.

COLUMN 10

Line 18, "element" should read --remaining element--, and "remain" should be deleted. Line 19, "ing" should be deleted.

COLUMN 14

Line 44, "wherein" should read --wherein, --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza

New York, New York 10112-3800

(212) 218-2100 - Telephone (212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

(Form#30) DWP/klm DC MAIN 260031v1

PATENT NO. 7,037,158 B2

No. of add'l. copies @ 30¢ per page

